L	Hits	Search Text	DB	Time stamp
Number -	1	20030106052.pn.	US-PGPUB	2004/09/13
_	1	20030106051.pn.	US-PGPUB	14:46 2004/09/13 14:46
-	1	6601165.pn.	USPAT	2004/09/13
-	396	717/168,172.ccls.	USPAT; US-PGPUB;	2004/09/13 14:49
_	626	712/11,13-15.ccls.	EPO; JPO; DERWENT; IBM_TDB USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/13 16:12
-	136	712/10.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/13 16:12
-	227	(install\$5 or updat\$3 or upgrad\$3) same firmware same (cell\$1 or node\$1)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/14
_	773	709/221.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT;	2004/09/14 10:05
_	3	("6023727" "5870610" "5623604").PN.	IBM_TDB USPAT	2004/09/14 08:10
_	40	(install\$5 or updat\$3 or upgrad\$3 or load\$3) same firmware and numa	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 09:58
-	126	<pre>(install\$5 or updat\$3 or upgrad\$3 or load\$3) same firmware same (multiprocess\$3 or cluster\$1)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
_	97	firmware same (cell\$1 or node\$1) same version\$1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 11:14
_	111	firmware same (cell\$1 or node\$1) same interconnect\$4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/14 10:39
_	21	(install\$5 or updat\$3 or upgrad\$3 or load\$3) same firmware same (high\$2 near availab\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 09:30
_	48	firmware same (manage\$7 with interconnect\$4)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
_	264	firmware and (cell\$1 or node\$1) and (install\$5 or updat\$3 or upgrad\$3) and (manage\$7 with interconnect\$4) and messag\$3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 08:33

_	17	("5113523" "5163052" "5175824" "5694607" "5701440" "5781434" "5907670" "5948087" "6088770" "6112271" "6243838" "6279046" "6289467" "6378021" "6378027"	USPAT	2004/09/16
-	66	"6453344" "6516372").PN. (install\$5 or updat\$3 or upgrad\$3 or load\$3) and firmware and rendezvous	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 09:30
_	4	("5694538" "5829013" "6081890" "6594723").PN.	USPAT	2004/09/16 09:31
_	120	<pre>(install\$5 or updat\$3 or upgrad\$3 or load\$3) same firmware same (multiprocess\$3 or cluster\$1 or cell\$1 or node\$1) same (interconnect\$4 or bus\$3)</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
-	171	<pre>(multiprocess\$3 or cluster\$1 or cell\$1 or node\$1) same ((manage\$7 or messag\$3 or config\$7) near (interconnect\$4 or bus\$3)) same ((fast or (high near speed) or data) near (interconnect\$4 or bus\$3))</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
-	39	<pre>(multiprocess\$3 or cluster\$1 or cell\$1 or node\$1) same ((slow or (low near speed)) near (interconnect\$4 or bus\$3)) same ((fast or (high near speed)) near (interconnect\$4 or bus\$3))</pre>	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
_	85	(updat\$3 or upgrad\$3) same numa	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16
-	110	(updat\$3 or upgrad\$3 or replac\$5) and firmware and numa	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/09/16 10:02
_	10	("5710907" "5727150" "5784697" "5787468" "5867649" "5931938" "6021479" "6047316" "6075938" "6081874").PN.	USPAT	2004/09/16
_	14		USPAT	2004/09/16 12:40